



**K.WEBBER
ELECTRICIAN**

Invoice

11/03/2022

Paistow and Ifold Parish Council
Winterton Hall. Loxwood Rd
Plaistow. W Sussex.
RH140PX

RE. Cricket Pavilion.

Dear Catherine.

Carried out an Electrical Installation Condition Report (EICR) on the Cricket Pavilion.

I have attached the Certificate with an Unsatisfactory Result to my Email.

My Findings as follows:

The Consumer Unit.

1.The Fuse board has various holes in its structure that are too big for safety reasons.

Because it has been fixed to a wooden backing board no fire sealant is evident. Recommendation is to Renew the board for a Modern Consumer with all the relevant Fire Retardant materials.

2. Colour Identification sleeving missing from conductors in the switches and ceiling roses.

Recommendation. Re-sleeve the conductors

Sunflower Cottage. Herons farm lane.
Kirdford, Billingshurst. West Sussex. RH140PR
Office 01403 820049 Mob 07860 129697



**K.WEBBER
ELECTRICIAN**

3. Cable Termination in loft ie Ceiling Rose with no cover.
Recommendation. Renew Light and Place a switch in the loft or by
Loft hatch with neon to indicate on or off.

Whilst Investigating In the Loft a cable was found live with no
junction box for protection ,this was terminated and made safe.

The Alarm needs attention either removed or renewed as it actuates
when a power failure happens. Also poor connection to alarm Siren
is evident.

Further Recommendation is to have smoke Alarms fitted with an
outside Neon as the building is made of wood and vulnerable to Fire.

For EICR and Parts Used.

£130.00

Trust to your satisfaction.

Yours Faithfully

K Webber

Bac details. MR K WEBBER

Account. 70937762

Sort code20-46-73

Sunflower Cottage. Herons farm lane.
Kirdford, Billingshurst. West Sussex. RH140PR
Office 01403 820049 Mob 07860 129697